

Supply Web – Defective Material Notifications (DMN)

<http://suppliers.deutzspain.com:8019/supplyWeb/account/login>

2016/01/14

The engine company.



Supply Web – Defective Material Notifications (DMN)

<http://suppliers.deutzspain.com:8019/supplyWeb/account/login>



Login

Language
English

Username
Cxxxxx

Password

Login Register

[Forgot Username or Password](#)

News

08-05-2014
[Noticias Deutz Spain](#)
09-05-2014
[Noticias Deutz AG](#)

Tips

The Infor Supplier Exchange online help contains step-by-step instruction and explanations of Infor Supplier Exchange components. To access the help, click "?" on the application's navigation bar.


Links





www.infor.com
[Manual Deutz Spain, S.A.](#)



- 1.- Select language.
- 2.- User: **Cxxxxx** (C=Quality y xxxxx = Supplier Nr.)
- 3.- Password: **Cxxxxx**

Supply Web – Defective Material Notifications (DMN)


<http://suppliers.deutzspain.com:8019/supplyWeb/account/login>



← → ↻    

 Infor Supplier Exchange® 11.4.6.024. Proveedor 99995 


Demand ▾ Shipments ▾ Receipts ▾ Defective Materials ▾ Delivery Performance ▾ Parts Per Million ▾ Supplier Performance ▾ Document Management ▾ More... ▾

◀ ⏪ ⏩ ▶ 

[Event Management Console](#) Overview EMC Last Update: 08.02.2016 13:30:19 CET

Welcome, Proveedor 99995.

For the most recent enhancements, read the [Release Notes](#).

 **Priority Items** Releases Purchase Orders Shipments Receipts Problem Reporting

Priority Items for 2-8-116


- [3 Unviewed Purchase Orders](#)
- [1 DMN requiring Containment Response](#)
- [1 DMN requiring Corrective Response](#)

Log out

The DMN are Quality claims.

Supply Web – Defective Material Notifications (DMN)

<http://suppliers.deutzspain.com:8019/supplyWeb/account/login>




infor Infor Supplier Exchange® 11.4.6.024. Proveedor 99995

Demand ▾ Shipments ▾ Receipts ▾ Defective Materials ▾ Delivery Performance ▾ Parts Per Million ▾ Supplier Performance ▾ Document Management ▾ More... ▾

Deutz Spain

Event Management Console Defective Material Notice




DMN requiring Containment Response 1 Total | 08.02.2016


View	Defective Material Notice ID	Facility	Ship To	Ship From	Part	Effective Date
	95	DEUTZ SPAIN ZAFRA	DEUTZ-ALM		99996666	08.02.2016

The **DMN 95** is the one we have opened for the present claim.
Click on the "glasses" for details


Supply Web – Defective Material Notifications (DMN)

<http://suppliers.deutzspain.com:8019/supplyWeb/account/login>

← → ↻   

 Infor Supplier Exchange® 11.4.6.024. Proveedor 99995 ↕

Demand ▾ Shipments ▾ Receipts ▾ Defective Materials ▾ Delivery Performance ▾ Parts Per Million ▾ Supplier Performance ▾ Document Management ▾ More... ▾

◀ ▶ 🏠 🖨️ 📄 ? 

Defective Materials DMN Edit

Facility	Ship To	Supplier
DEUTZ SPAIN ZAFRA Crta.Badajoz -Granada, Km 74,6 06300 ZAFRA (Badajoz) SPAIN	DEUTZ-ALM Calle Guadiana 38-40 Pol. Ind. Los Caños 06300 Zafra (Badajoz) SPAIN	Proveedor Test 99995 Pg Gracia 56 08007 Barcelona SPAIN

Part


Part Number: 99996666
Part Description: ART. TES PARA S.E. PEDIDO CERRADO

Header Information	Problem Description	Disposition	Supplier Information	Action Information	Claims	DMN History
DMN ID: 95 Reject Tag Number: 123456 Receipt Number: 123456 Receipt Date: 07.02.2016 Sample Quantity: 1,000 Rejected By: G. Gahete (DS-QL) Reason Code:Description: FM Falta de material/Lack of material						PO Number: 987654 Warning Only: No Received Quantity: 1,000 Rejected Quantity: 5 Quantity Non-Conforming: 10 Rejected Date: 07.02.2016 Source of Defect:Description: CR Control recepción/Incoming goods inspection

In "Problem Description" is where we put the basic information about the claim.
For details, photographs, ... we have attached an EXCEL file, similar to ARC file we have sent till now

Supply Web – Defective Material Notifications (DMN)

<http://suppliers.deutzspain.com:8019/supplyWeb/account/login>



The screenshot shows the Infor Supplier Exchange interface for a Defective Material Notification (DMN). The browser address bar displays the URL: suppliers.deutzspain.com:8019/supplyWeb/account/completeLogin. The page header includes the Infor logo and version information: "Infor Supplier Exchange® 11.4.6.024." and the supplier ID: "Proveedor 99995".

The main navigation menu includes: Demand, Shipments, Receipts, Defective Materials, Delivery Performance, Parts Per Million, Supplier Performance, Document Management, and More... The current page is titled "Defective Materials DMN Edit".

The "Facility" section shows: DEUTZ SPAIN ZAFRA, Crta.Badajoz -Granada, Km 74,6, 06300 ZAFRA (Badajoz), SPAIN. The "Ship To" section shows: DEUTZ-ALM, Calle Guadiana 38-40, Pol. Ind. Los Caños, 06300 Zafra (Badajoz), SPAIN. The "Supplier" section shows: Proveedor Test 99995, Pg Gracia 56, 08007 Barcelona, SPAIN.

The "Part" section displays: Part Number: 99996666, Part Description: ART. TES PARA S.E. PEDIDO CERRADO.

The "Action Information" tab is selected and circled in blue. Below it, the "Containment" section is expanded, showing: Response Required: Yes, Response Due Date: 09.02.2016. The "Containment Plan" field is circled in blue and has a blue arrow pointing to a text box: "Briefly describe the actions of the containment plan." The "Action Information" tab label has a blue arrow pointing to another text box: "In 'Action Information' you must define the containment and corrective actions." The "Containment Date" field is circled in blue and has a blue arrow pointing to a text box: "Containmentdate".


At the bottom of the form are "Update" and "Cancel" buttons.

Copyright © 2009 Infor. All rights reserved. The word and design marks set forth herein are trademarks and/or registered trademarks of Infor and/or related affiliates and subsidiaries. All rights reserved. All other trademarks listed herein are the property of their respective owners. www.infor.com.


Supply Web – Defective Material Notifications (DMN)

<http://suppliers.deutzspain.com:8019/supplyWeb/account/login>

← → ↻ 🔍 ☆ ☰

 Infor Supplier Exchange® 11.4.6.024. Proveedor 99995 ↗

Demand ▾ Shipments ▾ Receipts ▾ Defective Materials ▾ Delivery Performance ▾ Parts Per Million ▾ Supplier Performance ▾ Document Management ▾ More... ▾

◀ ⏪ ⏩ ▶ 

Defective Materials DMN Edit

Facility	Ship To	Supplier
DEUTZ SPAIN ZAFRA Ctra.Badajoz -Granada, Km 74,6 06300 ZAFRA (Badajoz) SPAIN	DEUTZ-ALM Calle Guadiana 38-40 Pol. Ind. Los Caños 06300 Zafra (Badajoz) SPAIN	Proveedor Test 99995 Pg Gracia 56 08007 Barcelona SPAIN

Part

Part Number: 99996666
Part Description: ART. TES PARA S.E. PEDIDO CERRADO

Header Information Problem Description Disposition Supplier Information **Action Information** Claims DMN History

Corrective Action

Response Required: Yes
Response Due Date: 12.02.2016

Corrective Plan:

Briefly describe the corrective actions

Corrective Date:

Corrective Status: None

First Corrected Shipment Date:

Customer Feedback:

Corrective date.

Supply Web – Defective Material Notifications (DMN)

<http://suppliers.deutzspain.com:8019/supplyWeb/account/login>

Browser address bar: suppliers.deutzspain.com:8019/supplyWeb/account/completeLogin

infor Infor Supplier Exchange® 11.4.6.024. Proveedor 99995

Navigation menu: Demand, Shipments, Receipts, Defective Materials, Delivery Performance, Parts Per Million, Supplier Performance, Document Management, More...

Search bar: Deutz Spain

Defective Materials DMN Edit

Facility	Ship To	Supplier
DEUTZ SPAIN ZAFRA Ctra.Badajoz -Granada, Km 74,6 06300 ZAFRA (Badajoz) SPAIN	DEUTZ-ALM Calle Guadiana 38-40 Pol. Ind. Los Caños 06300 Zafra (Badajoz) SPAIN	Proveedor Test 99995 Pg Gracia 56 08007 Barcelona SPAIN

Part

Part Number: 99996666
Part Description: ART. TES PARA S.E. PEDIDO CERRADO

- Header Information
- Problem Description
- Disposition
- Supplier Information
- Action Information**
- Claims
- DMN History

Corrective Date:

Corrective Status: None

First Corrected Shipment Date:

Customer Feedback:

Customer Template:
[formato 8D DS.xls 26.01.2016](#)

Supplier Attached Files: Ningún archivo seleccionado

To inform your action details we use a 8D format attached (as template) that you must fulfill

To save the changes, click "UPDATE"